

Oil Field Environmental Incident Summary

Incident: 20150725201304 **Date/Time of Notice:** 07/25/2015 20:13

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: CHICAGO 4-26H

Field Name: BANKS

Well File #: 23049

Date Incident: 7/25/2015

Time Incident: 13:00

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 99

Sec: 26

Qtr:

Location Description:

Submitted By: Shane Knuchel

Received By:

Contact Person: Shane Knuchel
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2	Barrels				
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

All fluid contained on well site.

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Line was isolated and repaired. Impacted material will be removed and taken to disposal.

Wastes Disposal Location: TBD

Agencies Involved: Notified Ashleigh Day NDIC by phone on 7/25/2015 at 07:00 PM.

Updates

Date: 7/27/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume: 2.00 barrels

Updated Other Volume:

Updated Other Contaminant

Notes:

Release contained within well pad. NDIC Oil & Gas retains oversight.

Date: 7/27/2015 **Status:** Reviewed - Assigned to Other Agency **Author:** O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a valve/piping connection leak, remained on the constructed well pad according to the report. NDIC Oil & Gas retains oversight.